

## How to solve material static issues?

### TSM Material Static Solution:

TSM use negatively charged air to de-charge material that has become statically charged through processing.

Images of the solution applied on our Gravimetric Batch Blenders are shown below:



- **Complete non-contact solution**
- **Proven & reliable solution**
- **Simple operation**
- **Enables faster material changeovers**
- **Ensures dosing ratios are consistently maintained and not interrupted due to static build up**



**Contact TSM today to get a proposal to solve your static issue!**